



2023 RESIDENTIAL HVAC FEDERAL STANDARD CHANGES

As a reminder, beginning Jan. 1, 2023, there will be updated performance standards and testing procedures in effect for central air conditioners and air source heat pumps. The update in performance standards will result in new rating efficiencies: SEER2, HSPF2, and EER2.

Efficiencies in the new SEER2/HSPF2 columns are approximately equivalent to the corresponding values in the old SEER/HSPF columns. For example, a new 13.4 SEER2 heat pump provides the equivalent savings as an old 14 SEER heat pump, and the old 14 SEER measure is appropriate for a new 13.4 SEER2 unit. See the charts below for more information or view the full MEMD Conversion Chart [here](#).

Heat Pumps

SEER	SEER2	Important Notes
14	13.4	Federal Standards to be phased out
15	14.3	New Federal Standard
16	15.2	New ENERGY STAR® requirement

HSPF	HSPF2	Important Notes
8.8	7.5	New Federal Standard
9.2	7.8	New ENERGY STAR® requirement

Air Conditioning

SEER	SEER2	Important Notes
14	13.4	New Federal Standard
16	15.2	New ENERGY STAR® requirement

If you have any questions, please contact your air conditioner or heat pump distributor for specific changes to stock products, or learn more on the [ENERGY STAR website](#).

Consumers Energy: 855-263-5390, consumershvac@icf.com

DTE: 855-539-1906, dtehvac@icf.com

ICF | 209 E. Washington Ave., Jackson, MI 49201

[Unsubscribe](#) keith.zimmerman@icf.com

[Update Profile](#) | [Constant Contact Data Notice](#)

Sent by consumershvac@icf.com in collaboration
with



Try email marketing for free today!